



OPEL Zafira: 1FME877			
Vinnnumber:	WOLPE9E38D2104980	Versionname:	ZAFIRA TOURER
First Registrationdate:	14/08/2013	Fiscalpower:	ecoFL.Cosmo S/S 136PK
Expertise Mileage:	142992	Power Kw:	100
Bodytype:	Hatchback	Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3706
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	Panoramic roof
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunction	Rear parking sensors
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear			
Summer tyres:	225/50/17/94 V LightMetal		
	Fr.L.	Continental: 4 mm	Fr.R.
		Continental: 4 mm	
	Re.L.	Continental: 5 mm	Re.R.
		Continental: 5 mm	

Assistance equipment	
Repair kit	Yes
Compressor	Yes
Total cost ex VAT	1267,34
Front bumper, Bad repair, Acceptable	0,00



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------






Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper F L, Scratch(es), Smart repair	110,64
---------------------------------------	--------



Door F R, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Alloy rim F R, Scratch(es), Acceptable	0,00
--	------



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	--------

