



MERCEDES C: 1DUR358				
Vinnumber:	WDD2042001F978615	Versionname:	C BRE 180 CDI BE	
First Registrationdate:	3/09/2012	Fiscalpower:	Optimum Ed.St/St 120PK	
Expertise Mileage:	138862	Power Kw:	88	
Bodytype:	Break	Body color	Grey	
Gearbox:	MAN 6 VIT	Paint type	Metalic	
Transmission:		Rims summer	Aluminium	
Fueltype:	Diesel	Oil level	OK	
Battery functioning	Yes	Parking lot	1431	
Number of doors	5			
Number of seats	5			
Number head rests	5			
Rims summer	Aluminium			
Category	Passenger Car			
Oil level	OK			
Options				
Radio CD		Central consol F		
Windows electric F		Luggage cover		
Windows electric R		Front parking sensors		
Cruise Control		Rear parking sensors		
Steering wheel multifunctional		Type of Tow bar	Tow bar fixed	
Type of headlighting	Headlighting Halogen			
Type of GPS	GPS big screen color			
Type of Lining	Lining leather			
Type of climate control	Autom climate control			
Limited Technical Inspection				
Airco functioning	OK	Battery functioning	Yes	
Tires wear profile	OK	Sound engine	OK	
Idle position	OK	Clutch test	OK	
Engine startingtime	OK	Wiper fluid level	OK	
Exhaust gass	OK	Lighting	OK	
Transmission	OK	Wiperblades	OK	
Handbrake	OK			
Degree of wear				
Winter tyres:	205/55/16/91 H LightMetal			
	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Fulda: 7 mm	Re.R.	Fulda: 7 mm
Assistance equipment				
Spare wheel	Yes	Jack	Yes	
Total cost ex VAT			1825,10	
Door F R, Scratch(es), Acceptable			0,00	
No pictures to display				
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)			95,00	
				
SD card, Missing, E - Replace			275,00	
No pictures to display				
Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)			211,80	



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Roof, Chemical polution, LI - Repair and paint (complete)	481,50
---	--------



Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Seat cover F L, Tear, E - Replace	360,00
-----------------------------------	--------

