







## SKODA Superb: 1GER415

Vinnumber: TMBJJ73T9E9034442 First Registrationdate: 17/01/2014 Expertise Mileage: 119640 Bodytype: Break Gearbox: MAN 5 VIT Transmission: Front Fueltype: Diesel Battery functioning Yes Number of doors 5 Number of seats 5 Number head rests 5 Rims summer Aluminium Category Passenger Car Oil level

Registration Certificate Car (BE)

Versionname: SUPERB COMBI Elegance Fiscalpower: Power Kw: 77 Body color Dark Grey Paint type Metalic Rims summer Aluminium Oil level OK Parking lot 3526

#### Options

Radio CD Steats R heated Windows electric F Seats electric F L Windows electric R Seats electric F R Steering wheel multifunctional Luggage cover Seats F heated Front parking sensors Radio multimedia Rear parking sensors

Yes

Type of headlighting Headlighting Xenon Type of Tow bar GPS big screen color Type of GPS Type of Lining Lining leather Type of climate control **Autom climate** 

Tow bar removible

## Limited Technical Inspection

Airco functioning Battery functioning ок Yes Tires wear profile Sound engine ок OK Clutch test Idle position OK OK Engine startingtime Wiper fluid level OK oĸ Exhaust gass Lighting OK OK Transmission Wiperblades OK oĸ Handbrake

control

# Degree of wear

	225/45/17/91 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

#### Assistance equipment

Spare wheel	Yes Jack	Yes
Total cost ex VAT	362,02	
Front bumper, Scratch(es), Accep	0,00	
No pictures to display		
Wing R R, Scratch(es), Acceptable	0,00	
No pictures to display		
Tailgate, Scratch(es), LI - Repair a	362,02	



