



BMW 5: 1EKF679			
Vinnnumber:	WBAXC01050DZ96163	Versionname:	5 GRAN TURISMO 520da
First Registrationdate:	3/01/2013	Fiscalpower:	St/St 163PK Aut.
Expertise Mileage:	173153	Power Kw:	120
Bodytype:	Hatchback	Body color	Dark Grey
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2228
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	Seats electric F L
Windows electric F	Seats electric F R
Windows electric R	Sun Roof electric
Cruise Control	Panoramic roof
Steering wheel multifunction	Central consol F
Seats F heated	Luggage cover
Radio multimedia	Front parking sensors
Type of headlighting	Rear parking sensors
Type of GPS	Headlighting Xenon
Type of Lining	GPS big screen color
Type of climate control	Lining leather
	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
Winter tyres:	245/45/19/102 V LightMetal			
	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm


Assistance equipment		
	Runflat	Yes
Total cost ex VAT		1673,04
Wing R R, Scratch(es), LI - Repair and paint (complete)		369,84



Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Door R R, Scratch(es), LI - Repair and paint (complete)	382,02
---	--------



Door F L, Scratch(es), LI - Repair and paint (complete)	382,02
---	--------



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

