



BMW 5: 1CMG631

Vinnnumber:	WBAMX11070DU46301	Versionname:	5 TOURING 520dA
First Registrationdate:	3/01/2012	Fiscalpower:	Start/Stop 163PK aut
Expertise Mileage:	132694	Power Kw:	120
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3410
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunction	
Seats F heated	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	225/55/17/97 H LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Dunlop: 4 mm	Re.R.	Dunlop: 4 mm

Assistance equipment

Runflat	Yes
---------	------------

Total cost ex VAT	535,00
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------




Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Interior, Dirty, Chemical cleaning	100,00
------------------------------------	--------



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display