


VOLKSWAGEN TOURAN: 1GAZ661

Vinnnumber:	WVGZZZ1TZEW040875	Versionname:	TOURAN
First Registrationdate:	15/11/2013	Fiscalpower:	
Expertise Mileage:	109585	Power Kw:	
Bodytype:		Body color	Silver
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	NOT OK
Maintenance	NOT OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	NOT OK		

Options

Radio CD		Sun Roof electric	
GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar removable
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	NOT OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	NOT OK
Idle position	NOT OK	Clutch test	NOT OK
Engine startingtime	NOT OK	Wiper fluid level	OK
Exhaust gass	NOT OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/91 T LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------


Total cost ex VAT 1198,84

Alloy rim R L polished, Damaged, E - Replace 235,20



Reflector, Damaged, E - Replace

12,00

No pictures to display	
Door R R, Scratch(es), Acceptable	0,00
No pictures to display	
Mirror side blinker R, Scratch(es), Acceptable	0,00
No pictures to display	
Engine, Not functioning (well), I - Repair	0,00
  	
	
Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00
  	
	
Tailgate, Bump(s), Acceptable	0,00
No pictures to display	
Front bumper, Scratch(es), Acceptable	0,00
No pictures to display	
Trunk lid covering R, Scratch(es), Smart repair	110,64
 	
Bumper R, Bump(s) and scratch(es), Le - Replace and paint	651,00
  	
  	
 	
Wing R R, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
  	

