



VOLKSWAGEN Sharan: 1DHP388

Vinnumber:	WVWZZZ7NZCV045293	Versionname:	TDI
First Registrationdate:	21/05/2012	Fiscalpower:	
Expertise Mileage:	111378	Power Kw:	103
Bodytype:		Body color	Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	SERVICE DANS 8300 KM	Parking lot	1113
Maintenance	OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD	Seats electric F L
GPS storage	Sun Roof electric
GPS storage HD	Panoramic roof
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Seats F heated	Type of Tow bar Tow bar removable
Radio multimedia	
Type of headlighting Headlighting Halogen	
Type of GPS GPS big screen color	
Type of Lining Lining leather and alcantara	
Type of climate control Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

Winter tyres:	225/60/17/98 V LightMetal			
	Fr.L.	Fulda: 7 mm	Fr.R.	Fulda: 7 mm
	Re.L.	Fulda: 6 mm	Re.R.	Fulda: 6 mm

Assistance equipment

	Runflat	Yes
Total cost ex VAT		218,50
Interior, Dirty, Cleaning		50,00





Side window R L, Damaged, E - Replace	95,60
---------------------------------------	-------



Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wing F L, Bad repair, P - Check	0,00
---------------------------------	------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display


Side window trim R L, Damaged, E - Replace	72,90
--	-------



Bumper R, Bad repair, P - Check	0,00
---------------------------------	------



Wing F R, Bad repair, P - Check	0,00
---------------------------------	------



Tailgate, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door R L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Tailgate, Strained , P - Check	0,00
--------------------------------	------

