


VOLKSWAGEN TOURAN: 1FUE905

Vinnnumber:	WVGZZZ1TZEW033913	Versionname:	D
First Registrationdate:	25/10/2013	Fiscalpower:	
Expertise Mileage:	89006	Power Kw:	77
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4726
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Spare tyre compact	Yes	Jack	Yes
--------------------	------------	------	------------

Total cost ex VAT	475,98
-------------------	---------------

Door R L, Bump(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Roof, Scratch(es), 67 - Polish	55,19
--------------------------------	--------------



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Wing R L, Bump(s), Acceptable	0,00
No pictures to display	
Bodywork, Dirty, P - Check	0,00
No pictures to display	
Bonnet, Chemical pollution, 67 - Polish	55,19



Door R R, Bump(s), Acceptable	0,00
No pictures to display	
Door F L, Bump(s), Acceptable	0,00
No pictures to display	
Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00



Windscreen, Stone chip(s), Windscreen repair	58,80
--	-------

