



VOLKSWAGEN Sharan: 1GHM394			
Vinnnumber:	WVWZZZ7NZE023836	Versionname:	SHARAN Comfortline 140PK
First Registrationdate:	10/02/2014	Fiscalpower:	
Expertise Mileage:	108737	Power Kw:	103
Bodytype:	MPV	Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2805
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options			
Radio CD		Sun Roof electric	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear			
Winter tyres:	215/60/16/95 V LightMetal		
	Fr.L.	Dunlop: 6 mm	Fr.R.
			Dunlop: 6 mm
	Re.L.	Dunlop: 7 mm	Re.R.
			Dunlop: 7 mm

Assistance equipment	
Total cost ex VAT	1498,18
Front bumper, Bump(s), LI - Repair and paint (complete)	302,16



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	382,02
---	--------



Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	------

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	369,84
---	--------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

