



TOYOTA Hilux: 405BYY			
Vinnnumber:	AHTFR22G006025728	Versionname:	HILUX 4WD Double Cab S 144PK
First Registrationdate:	27/08/2010	Fiscalpower:	
Expertise Mileage:	116804	Power Kw:	106
Bodytype:	Pick-Up	Body color	White
Gearbox:	MAN 5 VIT	Paint type	Opaque
Transmission:	4 Weel	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1622
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Light Commercial Vehicle		
Oil level	OK		

Options		
Type of headlighting	Headlighting Halogen	Central consol F
Type of Lining	Lining fabrics	

Limited Technical Inspection			
Tires wear profile	OK	Battery functioning	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Transmission	OK	Lighting	OK
Handbrake	OK	Wiperblades	OK

Degree of wear				
Summer tyres:	205/80/16/104 T Steel			
	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			2172,21
Bumper R, Damaged, E - Replace			772,00




Alloy Rims (all), Rust, Acceptable	0,00
------------------------------------	------



Wing R L, Bump(s), LI - Repair and paint (complete)	231,15
---	--------



Seat cover F L, Damaged, E - Replace	300,00
--------------------------------------	--------



Bumper corner R L, Bump(s), It - Spot repair	115,56
--	--------



Floor covering F L, Damaged, E - Replace	272,00
--	--------



Radio, Missing, E - Replace	210,00
-----------------------------	--------



Boot carpet, Chemical polution, Acceptable	0,00
--	------



Bodywork, Not original part, Acceptable	0,00
---	------

No pictures to display

Luggage space cover, Missing, E - Replace	180,00
---	--------

No pictures to display

Door panel F L, Damaged, E - Replace	91,50
--------------------------------------	-------

