



CITRO?N C4 Picasso: 1GWE734

Vinnnumber:	VF73E9HC8EJ644118	Versionname:	GR.C4 PICASSO Intensive
First Registrationdate:	16/05/2014	Fiscalpower:	ETG 115PK Aut.
Expertise Mileage:	112562	Power Kw:	85
Bodytype:		Body color	Grey
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3118
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage		Central consol F
GPS storage	HD	Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/17/95 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Pirelli: 7 mm	Re.R.	Pirelli: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			590,72
Wing R L, Scratch(es), Acceptable			0,00

No pictures to display


Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	--------------



Trunk lid covering R, Scratch(es), Smart repair	110,64
---	---------------




Bonnet, Scratch(es), LI - Repair and paint (complete)	290,08
---	--------



Front bumper, Bump(s), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R R, Bad repair, Acceptable	0,00
----------------------------------	------



Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------

