


**AUDI A1: 1GKN192**

Vinnumber:	<b>WAUZZZ8X4EB061511</b>	Versionname:	<b>A1 SB Attraction 90PK</b>
First Registrationdate:	<b>4/03/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>82924</b>	Power Kw:	<b>66</b>
Bodytype:		Body color	<b>Light Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type	<b>Metalic</b>
Transmission:		Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>3623</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD	Luggage cover
Windows electric F	Rear parking sensors
Windows electric R	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Xenon</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**


<b>215/40/17/87 V LightMetal</b>			
Winter tyres:	Fr.L.	Fr.R.	Dunlop: 5 mm
	Re.L.	Re.R.	Dunlop: 6 mm

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT	<b>768,88</b>		
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>		



<b>Alloy rim R R, Scratch(es), LI - Repair and paint (complete)</b>	<b>95,00</b>
---	--------------



<b>Alloy rim F L, Scratch(es), LI - Repair and paint (complete)</b>	<b>95,00</b>
---	--------------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Boot carpet, Dirty, Cleaning

25,00



Front bumper, Scratch(es), LI - Repair and paint (complete)

169,44



Tailgate, Scratch(es), Acceptable

0,00

No pictures to display

Seat cover F R, Dirty, Cleaning

25,00



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)

169,44

