




OPEL Astra: 1EPO863			
Vinnnumber:	W0LPC8DA3D8036732	Versionname:	ASTRA BRE ecoFLEX
First Registrationdate:	1/01/2020	Fiscalpower:	Essentia S&S 95PK
Expertise Mileage:	194718	Power Kw:	70
Bodytype:	Break	Body color	Black
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2509
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	Luggage cover
Windows electric F	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear			
Summer tyres:	205/60/16/91 V Steel		
	Fr.L.	Michelin: 4 mm	Fr.R.
	Re.L.	Michelin: 5 mm	Re.R.
		Michelin: 4 mm	Michelin: 5 mm

Assistance equipment			
Spare tyre compact	Yes	Jack	Yes
Total cost ex VAT			1088,53
Wing R R, Scratch(es), Acceptable			0,00
No pictures to display			
Interior, Dirty, Cleaning			100,00



Ignition key, Missing, E - Replace		150,00
No pictures to display		
Door R R, Scratch(es), Acceptable		0,00
No pictures to display		
Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete)		318,35

		
Wing F R, Scratch(es), LI - Repair and paint (complete)		220,18
		
Certificate Of Conformity, Missing, E - Replace		150,00
No pictures to display		
Bumper R, Scratch(es), Acceptable		0,00
No pictures to display		
Registration Document, Missing, E - Replace		150,00
No pictures to display		