



OPEL Astra: 1FRH195			
Vinnnumber:	W0LPD8EW2E8008333	Versionname:	ASTRA BRE ecoFLEX Business 110PK
First Registrationdate:	1/10/2013	Fiscalpower:	
Expertise Mileage:	175429	Power Kw:	81
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1710
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options			
Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Rear parking sensors	
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
Winter tyres:	215/60/16/98 H Steel			
	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 6 mm
	Re.L.	Goodyear: 8 mm	Re.R.	Goodyear: 8 mm

Assistance equipment			
Spare tyre compact	Yes	Jack	Yes
Total cost ex VAT			750,00
Inner door handle F R, Scratch(es), Acceptable			0,00
No pictures to display			
Wheel cover F L, Scratch(es), Acceptable			0,00
No pictures to display			
Door F L, Scratch(es), Acceptable			0,00
No pictures to display			
Wheel cover R R, Scratch(es), Acceptable			0,00
No pictures to display			
Tailgate, Hail damage, PDR - Hail			250,00






Wheel cover F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Roof, Hail damage, PDR - Hail	375,00
-------------------------------	--------



Floor covering F L, Hole, Acceptable	0,00
--------------------------------------	------

No pictures to display

Inner door handle F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing F L, Stone chip(s), Acceptable	0,00
-------------------------------------	------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bonnet, Hail damage, PDR - Hail	125,00
---------------------------------	--------

