



|                                                                                     |                           |                                                                                     |                         |              |
|-------------------------------------------------------------------------------------|---------------------------|-------------------------------------------------------------------------------------|-------------------------|--------------|
| PEUGEOT 308: 1GAB087                                                                |                           |                                                                                     |                         |              |
| Vinnumber:                                                                          | VF34H9HD8DS205063         | Versionname:                                                                        | 308 SW e-HDi Active STT |              |
| First Registrationdate:                                                             | 3/12/2013                 | Fiscalpower:                                                                        | 115PK                   |              |
| Expertise Mileage:                                                                  | 133959                    | Power Kw:                                                                           | 84                      |              |
| Bodytype:                                                                           |                           | Body color                                                                          | Blue                    |              |
| Gearbox:                                                                            | MAN 6 VIT                 | Paint type                                                                          | Metalic                 |              |
| Transmission:                                                                       | Front                     | Rims summer                                                                         | Aluminium               |              |
| Fueltype:                                                                           | Diesel                    | Oil level                                                                           | OK                      |              |
| Battery functioning                                                                 | Yes                       | Parking lot                                                                         | 2426                    |              |
| Number of doors                                                                     | 5                         |                                                                                     |                         |              |
| Number of seats                                                                     | 5                         |                                                                                     |                         |              |
| Number head rests                                                                   | 5                         |                                                                                     |                         |              |
| Rims summer                                                                         | Aluminium                 |                                                                                     |                         |              |
| Category                                                                            | Passenger Car             |                                                                                     |                         |              |
| Oil level                                                                           | OK                        |                                                                                     |                         |              |
| Registration Certificate Car (BE)                                                   | Yes                       |                                                                                     |                         |              |
| Options                                                                             |                           |                                                                                     |                         |              |
| Radio CD                                                                            |                           | Panoramic roof                                                                      |                         |              |
| GPS storage                                                                         | HD                        | Central consol F                                                                    |                         |              |
| Windows electric F                                                                  |                           | Luggage cover                                                                       |                         |              |
| Windows electric R                                                                  |                           | Front parking sensors                                                               |                         |              |
| Cruise Control                                                                      |                           | Rear parking sensors                                                                |                         |              |
| Type of headlighting                                                                | Headlighting Halogen      | Type of Tow bar                                                                     | Tow bar fixed           |              |
| Type of GPS                                                                         | GPS big screen color      |                                                                                     |                         |              |
| Type of Lining                                                                      | Lining fabrics            |                                                                                     |                         |              |
| Type of climate control                                                             | Autom climate control     |                                                                                     |                         |              |
| Limited Technical Inspection                                                        |                           |                                                                                     |                         |              |
| Airco functioning                                                                   | OK                        | Battery functioning                                                                 | Yes                     |              |
| Tires wear profile                                                                  | OK                        | Sound engine                                                                        | OK                      |              |
| Idle position                                                                       | OK                        | Clutch test                                                                         | OK                      |              |
| Engine startingtime                                                                 | OK                        | Wiper fluid level                                                                   | OK                      |              |
| Exhaust gass                                                                        | OK                        | Lighting                                                                            | OK                      |              |
| Transmission                                                                        | OK                        | Wiperblades                                                                         | OK                      |              |
| Handbrake                                                                           | OK                        |                                                                                     |                         |              |
| Degree of wear                                                                      |                           |                                                                                     |                         |              |
| Winter tyres:                                                                       | 225/45/17/91 H LightMetal |                                                                                     |                         |              |
|                                                                                     | Fr.L.                     | Dunlop: 5 mm                                                                        | Fr.R.                   | Dunlop: 5 mm |
|                                                                                     | Re.L.                     | Dunlop: 3 mm                                                                        | Re.R.                   | Dunlop: 3 mm |
| Assistance equipment                                                                |                           |                                                                                     |                         |              |
| Spare wheel                                                                         | Yes                       |                                                                                     |                         |              |
| Total cost ex VAT                                                                   |                           |                                                                                     | 670,08                  |              |
| Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)               |                           |                                                                                     | 95,00                   |              |
|  |                           |  |                         |              |
| Bumper R, Scratch(es), Acceptable                                                   |                           |                                                                                     | 0,00                    |              |
| No pictures to display                                                              |                           |                                                                                     |                         |              |
| Door R L, Scratch(es), Acceptable                                                   |                           |                                                                                     | 0,00                    |              |
| No pictures to display                                                              |                           |                                                                                     |                         |              |
| Bonnet, Chemical polution, LI - Repair and paint (complete)                         |                           |                                                                                     | 290,08                  |              |



|                                               |      |
|-----------------------------------------------|------|
| Wing R R, Bump(s) and scratch(es), Acceptable | 0,00 |
|-----------------------------------------------|------|

No pictures to display

|                                                                       |       |
|-----------------------------------------------------------------------|-------|
| Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|-----------------------------------------------------------------------|-------|



|                                                                       |       |
|-----------------------------------------------------------------------|-------|
| Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|-----------------------------------------------------------------------|-------|



|                                                 |      |
|-------------------------------------------------|------|
| Rocker panel inner R R, Scratch(es), Acceptable | 0,00 |
|-------------------------------------------------|------|

No pictures to display

|                                                                       |       |
|-----------------------------------------------------------------------|-------|
| Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|-----------------------------------------------------------------------|-------|

