



|                                   |                   |              |                         |
|-----------------------------------|-------------------|--------------|-------------------------|
| MERCEDES C BREAK: 1JPV593         |                   |              |                         |
| Vinnumber:                        | WDD2052041F160938 | Versionname: | 2.1 C 220 BLUETEC 120KW |
| First Registrationdate:           | 3/02/2015         | Fiscalpower: |                         |
| Expertise Mileage:                | 174792            | Power Kw:    | 120                     |
| Bodytype:                         | Break             | Body color   | Black                   |
| Gearbox:                          | Automatic         | Paint type   | Metalic                 |
| Transmission:                     |                   | Rims summer  | Aluminium               |
| Fueltype:                         | Diesel            | Oil level    | OK                      |
| Battery functioning               | Yes               | Parking lot  | 1406                    |
| Number of doors                   | 5                 |              |                         |
| Number of seats                   | 5                 |              |                         |
| Number head rests                 | 5                 |              |                         |
| Rims summer                       | Aluminium         |              |                         |
| Category                          | Passenger Car     |              |                         |
| Oil level                         | OK                |              |                         |
| Registration Certificate Car (BE) | Yes               |              |                         |

|                                |                       |
|--------------------------------|-----------------------|
| Options                        |                       |
| Radio CD                       | Central consol F      |
| Windows electric F             | Luggage cover         |
| Windows electric R             | Front parking sensors |
| Cruise Control                 | Rear parking sensors  |
| Steering wheel multifunctional |                       |
| Type of headlighting           | Headlighting Halogen  |
| Type of GPS                    | GPS big screen color  |
| Type of Lining                 | Lining fabrics        |
| Type of climate control        | Autom climate control |

|                              |    |                     |     |
|------------------------------|----|---------------------|-----|
| Limited Technical Inspection |    |                     |     |
| Airco functioning            | OK | Battery functioning | Yes |
| Tires wear profile           | OK | Sound engine        | OK  |
| Idle position                | OK | Clutch test         | OK  |
| Engine startingtime          | OK | Wiper fluid level   | OK  |
| Exhaust gass                 | OK | Lighting            | OK  |
| Transmission                 | OK | Wiperblades         | OK  |
| Handbrake                    | OK |                     |     |

|                |                           |                  |       |                  |
|----------------|---------------------------|------------------|-------|------------------|
| Degree of wear |                           |                  |       |                  |
| Winter tyres:  | 205/60/16/92 H LightMetal |                  |       |                  |
|                | Fr.L.                     | Vredestein: 6 mm | Fr.R. | Vredestein: 6 mm |
|                | Re.L.                     | Vredestein: 4 mm | Re.R. | Vredestein: 4 mm |

|                                                              |     |            |        |
|--------------------------------------------------------------|-----|------------|--------|
| Assistance equipment                                         |     |            |        |
| Repair kit                                                   | Yes | Compressor | Yes    |
| Total cost ex VAT                                            |     |            | 215,00 |
| Alloy rim R L, Scratch(es), LI - Repair and paint (complete) |     |            | 95,00  |



|                                 |       |
|---------------------------------|-------|
| Seat cover F R, Dirty, Cleaning | 25,00 |
|---------------------------------|-------|



|                                                              |       |
|--------------------------------------------------------------|-------|
| Alloy rim F L, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--------------------------------------------------------------|-------|



|                                   |      |
|-----------------------------------|------|
| Door F R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

*No pictures to display*

|                                   |      |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

*No pictures to display*