



MAZDA CX-5: 1JNG654			
Vinnnumber:	JMZKEF91600317889	Versionname:	2.2 CDVI 110KW SENSE
First Registrationdate:	23/01/2015	Fiscalpower:	
Expertise Mileage:	49867	Power Kw:	110
Bodytype:	SUV	Body color	Dark Red
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2213
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
Winter tyres:	225/55/17/102 T LightMetal			
	Fr.L.	Pirelli: 6 mm	Fr.R.	Pirelli: 6 mm
	Re.L.	Pirelli: 7 mm	Re.R.	Pirelli: 7 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			472,44
Bumper R, Bump(s), LI - Repair and paint (complete)			211,80



Tailgate, Scratch(es), Acceptable	0,00
No pictures to display	

Certificate Of Conformity, Missing, E - Replace	150,00
No pictures to display	
Wing F L, Scratch(es), Acceptable	0,00
No pictures to display	
Front bumper, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper R, Bump(s), Smart repair	110,64

