



MERCEDES B: 1GES891			
Vinnnumber:	WDD2462121J231120	Versionname:	B 180 CDI BE 109PK
First Registrationdate:	17/01/2014	Fiscalpower:	
Expertise Mileage:	88737	Power Kw:	80
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Body color	ZWART
Transmission:	Front	Paint type	Metalic
Fueltype:	Diesel	Rims summer	Steel
Maintenance	OK	Oil level	OK
Maintenance	SERV A 313 DAGEN	Parking lot	3711
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		
Options			
Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		
Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		
Degree of wear			
Winter tyres:	195/65/15/91 T Steel		
	Fr.L.	Continental: 5 mm	Fr.R.
		Continental: 5 mm	
	Re.L.	Continental: 5 mm	Re.R.
Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			468,60
Wheel cover F R, Scratch(es), E - Replace			30,00
Windscreen, Stone chip(s), Windscreen repair			58,80



Front bumper, Scratch(es), LI - Repair and paint (complete)

211,80



Seat cover F L, Stain, Cleaning

25,00



Seat cover R, Stain, Cleaning

25,00



Wheel cover R R, Scratch(es), E - Replace

30,00



Seat cover F R, Stain, Cleaning

25,00



Wing R L, Bump(s), PDR - Knock out without painting

63,00

