



MERCEDES C: 1DSD882			
Vinnumber:	WDD2042001F970516	Versionname:	C BRE 180 CDI BE
First Registrationdate:	8/08/2012	Fiscalpower:	Optimum Ed.St/St 120PK
Expertise Mileage:	92396	Power Kw:	88
Bodytype:	Break	Body color	Dark Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2404
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
Summer tyres:	205/55/16/91 V LightMetal			
	Fr.L.	Yokohama: 4 mm	Fr.R.	Yokohama: 4 mm
	Re.L.	Bridgestone: 3 mm	Re.R.	Bridgestone: 3 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			1902,68
Seat cover F R, Dirty, Cleaning			25,00



Tailgate, Bump(s) and scratch(es), Le - Replace and paint	1034,68
---	---------





Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



GPS disc, Missing, E - Replace	275,00
--------------------------------	--------

No pictures to display

Rear window, Scratch(es), Acceptable	0,00
--------------------------------------	------

No pictures to display

Rearview mirror R complete, Damaged, Le - Replace and paint	283,00
---	--------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

