



KIA Cee'd: 1GEE120			
Vinnnumber:	U5YHM816AEL077547	Versionname:	CEE'D SW Business Line '1'
First Registrationdate:	14/01/2014	Fiscalpower:	ISG 110PK
Expertise Mileage:	119461	Power Kw:	81
Bodytype:		Body color	White
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2526
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
Summer tyres:	195/65/15/91 T Steel			
	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 6 mm
	Re.L.	Bridgestone: 3 mm	Re.R.	Bridgestone: 3 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			1732,24
Wheel cover F R, Scratch(es), E - Replace			30,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------

  		
 		
Interior, Dirty, Cleaning		50,00
 		
Front bumper, Scratch(es), LI - Repair and paint (complete)		211,80
  		
  		
Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete)		310,50
 		
Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete)		220,18
 		
Bonnet, Bump(s), Acceptable		0,00
No pictures to display		
Door R R, Scratch(es), LI - Repair and paint (complete)		0,00
 		
Rocker panel inner R L, Bump(s) and scratch(es), LI - Repair and paint (complete)		115,56
 		
Floor covering F L, Hole, Smart repair		64,32
 		
Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)		115,56



Floor covering F L, Hole, Smart repair	64,32
--	-------



Bodywork, Not original part, Acceptable	0,00
---	------

No pictures to display

Wheel cover R R, Scratch(es), E - Replace	30,00
---	-------

