



OPEL Astra: 1ENA714

Vinnnumber:	WOLPE8EX7D8030557	Versionname:	ecoFLEX Cosmo St/St
First Registrationdate:	28/01/2013		130PK
Expertise Mileage:	91185	Fiscalpower:	
Bodytype:	Break	Power Kw:	96
Gearbox:	MAN 6 VIT	Body color	Black
Transmission:	Front	Paint type	Metalic
Fueltype:	Diesel	Rims summer	Aluminium
Maintenance	SERVICE GEDAAN OP 77009	Oil level	OK
	KM	Parking lot	1111
Maintenance	OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	No		

Options

Radio CD	Central consol F
GPS storage	SD
GPS storage	Luggage cover
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

225/50/17/94 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.
	Re.L.	Michelin: 5 mm	Re.R.

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	-----	------------	-----

Total cost ex VAT	0,00
Seat cover R, Stain, Cleaning	0,00



Boot carpet, Stain, Cleaning	0,00
------------------------------	------



Seat cover F R, Stain, Cleaning	0,00
---------------------------------	------



Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display