



PEUGEOT 208: 1EPX713			
Vinnumber:	VF3CC9HP0DT009801	Versionname:	208 BER e-HDi Active
First Registrationdate:	19/02/2013	Fiscalpower:	92PK
Expertise Mileage:	117035	Power Kw:	68
Bodytype:	Hatchback	Body color	Black
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4615
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options			
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F			
Cruise Control			
Steering wheel multifunction			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
Winter tyres:	185/65/15/88 T Steel			
	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			678,00
Door F R, Scratch(es), Acceptable			0,00
No pictures to display			
Door seal F L, Tear, E - Replace			48,00



Interior, Stain, Cleaning	100,00
---------------------------	--------





Front bumper, Scratch(es), LI - Repair and paint (complete)	169,44
---	--------



Rear spoiler, Bump(s), LI - Repair and paint (complete)	163,56
---	--------



Bumper grille, Broken, E - Replace	109,00
------------------------------------	--------



Roof, Scratch(es), Acceptable	0,00
-------------------------------	------

No pictures to display

Roof, Scratch(es), Acceptable	0,00
-------------------------------	------

No pictures to display

Wheel cover F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wheel cover R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wheel cover F R, Damaged, E - Replace	24,00
---------------------------------------	-------



Windscreen, Stone chip(s), Acceptable	0,00
---------------------------------------	------

No pictures to display

Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	------

No pictures to display

Trunk lid covering R, Scratch(es), E - Replace	64,00
--	-------





Wing R R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door F L, Bad repair, LI - Repair and paint (complete)	0,00
--	------



Door R R, Bump(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Ceiling, Scratch(es), Acceptable	0,00
----------------------------------	------

No pictures to display