




MERCEDES B: 1FWH027			
Vinnnumber:	WDD2462001J218185	Versionname:	B 180 CDI BE 7G-DCT 109PK Aut.
First Registrationdate:	18/11/2013	Fiscalpower:	
Expertise Mileage:	79966	Power Kw:	80
Bodytype:		Body color	Light Grey
Gearbox:	Automatic	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1222
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
Summer tyres:	225/45/17/94 V LightMetal			
	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment	
Repair kit	Yes
Compressor	Yes
Total cost ex VAT	401,80
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

