



MERCEDES CLA: 1HJH473				
Vinnumber:	WDD1173121N119484	Versionname:	CLA BER 180 CDI 109PK	
First Registrationdate:	1/08/2014	Fiscalpower:		
Expertise Mileage:	116579	Power Kw:	80	
Bodytype:	Berline	Body color	Black	
Gearbox:	MAN 6 VIT	Paint type	Metalic	
Transmission:	Front	Rims summer	Aluminium	
Fueltype:	Diesel	Oil level	OK	
Battery functioning	Yes	Parking lot	2731	
Number of doors	5			
Number of seats	5			
Number head rests	5			
Rims summer	Aluminium			
Category	Passenger Car			
Oil level	OK			
Registration Certificate Car (BE)	Yes			
Options				
Radio CD		Central consol F		
Windows electric F		Front parking sensors		
Windows electric R		Rear parking sensors		
Cruise Control				
Steering wheel multifunctional				
Radio multimedia				
Type of headlighting	Headlighting Halogen			
Type of GPS	GPS big screen color			
Type of Lining	Lining semi-leather			
Type of climate control	Manual climate control			
Limited Technical Inspection				
Airco functioning	OK	Battery functioning	Yes	
Tires wear profile	OK	Sound engine	OK	
Idle position	OK	Clutch test	OK	
Engine startingtime	OK	Wiper fluid level	OK	
Exhaust gass	OK	Lighting	OK	
Transmission	OK	Wiperblades	OK	
Handbrake	OK			
Degree of wear				
Summer tyres:	205/55/16/91 H LightMetal			
	Fr.L.	Yokohama: 4 mm	Fr.R.	Yokohama: 4 mm
	Re.L.	Yokohama: 5 mm	Re.R.	Yokohama: 5 mm
Assistance equipment				
Repair kit	Yes	Compressor	Yes	
Total cost ex VAT			1449,08	
Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)			211,80	
				
Sill outer L, Bump(s) and scratch(es), LI - Repair and paint (complete)			310,50	



Door R L, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	--------



Door F R, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------

