



KIA Carens: 1GEE118

Vinnnumber:	KNAHU815AE7050457	Versionname:	CARENS Fusion 136PK
First Registrationdate:	14/01/2014	Fiscalpower:	
Expertise Mileage:	69136	Power Kw:	100
Bodytype:	Hatchback	Body color	White
Gearbox:	MAN 6 VIT	Paint type	Opaque
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3816
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/91 MS LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 3 mm	Fr.R.	Uniroyal: 3 mm
	Re.L.	Uniroyal: 3 mm	Re.R.	Uniroyal: 3 mm

Assistance equipment

Total cost ex VAT	741,95
Roof, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------

