



MERCEDES A: 1HKE939				
Vinnnumber:	WDD1760111V024300	Versionname:	A 160 CDI 90PK	
First Registrationdate:	7/08/2014	Fiscalpower:		
Expertise Mileage:	128812	Power Kw:	66	
Bodytype:	Hatchback	Body color	Dark Grey	
Gearbox:	MAN 6 VIT	Paint type	Metalic	
Transmission:	Front	Rims summer	Steel	
Fueltype:	Diesel	Oil level	OK	
Battery functioning	Yes	Parking lot	3806	
Number of doors	5			
Number of seats	5			
Number head rests	5			
Rims summer	Steel			
Category	Passenger Car			
Oil level	OK			
Registration Certificate Car (BE)	Yes			
Options				
Radio CD		Central consol F		
Windows electric F		Luggage cover		
Windows electric R				
Steering wheel multifunctional				
Radio multimedia				
Type of headlighting	Headlighting Halogen			
Type of GPS	GPS big screen color			
Type of Lining	Lining fabrics			
Type of climate control	Manual climate control			
Limited Technical Inspection				
Airco functioning	OK	Battery functioning	Yes	
Tires wear profile	OK	Sound engine	OK	
Idle position	OK	Clutch test	OK	
Engine startingtime	OK	Wiper fluid level	OK	
Exhaust gass	OK	Lighting	OK	
Transmission	OK	Wiperblades	OK	
Handbrake	OK			
Degree of wear				
	195/65/15/91 V Steel			
Summer tyres:	Fr.L.	Kleber: 4 mm	Fr.R.	Kleber: 4 mm
	Re.L.	Kleber: 5 mm	Re.R.	Kleber: 5 mm
Assistance equipment				
Repair kit	Yes	Compressor	Yes	
Total cost ex VAT			750,60	
Tailgate, Bump(s), PDR - Knock out without painting			63,00	
Door panel R L, Damaged, E - Replace			114,00	
Wheel cover F R, Scratch(es), Acceptable			0,00	
No pictures to display				

Wheel cover F L, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80
	
Wheel cover R R, Scratch(es), Acceptable	0,00
No pictures to display	
Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
	
Ignition key, Missing, E - Replace	150,00
No pictures to display	