


MERCEDES C-CLASSE: 1FRG540

Vinnnumber:	WDD2040021A906907	Versionname:	220 CDI BE Edition Avantgarde
First Registrationdate:	1/10/2013	Fiscalpower:	
Expertise Mileage:	139767	Power Kw:	120
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	2230
Maintenance	B5 DANS 14.300 KM		
Battery functioning	Yes		
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
GPS storage	HD Front parking sensors
GPS storage	Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-leather

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/91 T LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Spare tyre compact	Yes	Jack	Yes
--------------------	------------	------	------------

Total cost ex VAT	729,35
Wing F L, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror housing R, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Outer door handle F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Daytime running lights R, Stone chip(s), E - Replace	172,35



Inner door handle F R, Damaged, Acceptable

0,00

inner door handle r R, Damaged, Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Bump(s), PDR - Knock out without painting	63,00
	
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
	
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Repaired, P - Check	0,00
	
Rearview mirror housing L, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror basis R, Difference in color, Acceptable	0,00
<i>No pictures to display</i>	
Seat cover F L, Worn, Acceptable	0,00
<i>No pictures to display</i>	
Door panel F L, Tear, E - Replace	114,00
	
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Roof, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Outer door handle R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F R, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

