



PEUGEOT 508: 1CPQ303				
Vinnumber:	VF38E9HD8CL060215	Versionname:		
First Registrationdate:	18/07/2012	Fiscalpower:		
Expertise Mileage:	176343	Power Kw:	84	
Bodytype:	Break	Body color	Dark Grey	
Gearbox:	Automatic	Paint type	Metalic	
Transmission:	Front	Rims summer	Aluminium	
Fueltype:	Diesel	Oil level	OK	
Battery functioning	Yes	Parking lot	TRU20	
Number of doors	5			
Number of seats	5			
Number head rests	5			
Rims summer	Aluminium			
Category	Passenger Car			
Oil level	OK			
Registration Certificate Car (BE)	Yes			
Options				
Radio CD		Seats electric F L		
Windows electric F		Seats electric F R		
Windows electric R		Panoramic roof		
Cruise Control		Central consol F		
Steering wheel multifunctional		Luggage cover		
Seats F heated		Front parking sensors		
Radio multimedia		Rear parking sensors		
Type of headlighting	Headlighting Halogen			
Type of GPS	GPS big screen color			
Type of Lining	Lining leather			
Type of climate control	Autom climate control			
Head-up Display				
Limited Technical Inspection				
Airco functioning	OK	Battery functioning	Yes	
Tires wear profile	OK	Sound engine	OK	
Idle position	OK	Clutch test	NOT OK	
Engine startingtime	OK	Wiper fluid level	OK	
Exhaust gass	OK	Lighting	OK	
Transmission	NOT OK	Wiperblades	OK	
Handbrake	OK			
Degree of wear				
	215/55/17/98 V LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm
Assistance equipment				
Spare wheel	Yes	Jack	Yes	
Total cost ex VAT			848,35	
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)			95,00	
				
Bumper R, Scratch(es), Acceptable			0,00	
No pictures to display				
Door F L, Scratch(es), LI - Repair and paint (complete)			318,35	



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display

Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

