



CITRO?N GRAND C4 PICASSO: 1LBD584

Vinnnumber:	VF73EAHXTFJ727495	Versionname:	2.0 BLUEHDI 150 S/S EXCLUSIVE AUTO
First Registrationdate:	7/08/2015	Fiscalpower:	
Expertise Mileage:	157951	Power Kw:	110
Bodytype:	MPV	Body color	Silver
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4528
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

TV/DVD screen R		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	205/55/17/95 H LightMetal			
Winter tyres:	Fr.L.	Vredestein: 3 mm	Fr.R.	Vredestein: 3 mm
	Re.L.	Vredestein: 3 mm	Re.R.	Vredestein: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			395,00
Door F R, Bump(s), Acceptable			0,00
<i>No pictures to display</i>			
Bumper R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Rearview mirror housing L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)			95,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Aerial, Damaged, E - Replace 15,00



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00

