



PEUGEOT Boxer 335: 598ALB

Vinnumber:	VF3YCAMFB11631191	Versionname:	BOXER 335 B/F MWB HR L2H2 101PK
First Registrationdate:	27/04/2009	Fiscalpower:	
Expertise Mileage:	31263	Power Kw:	74
Bodytype:		Body color	White
Gearbox:	MAN 6 VIT	Paint type	Opaque
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	LCV10
Number of doors	6		
Number of seats	3		
Number head rests	3		
Rims summer	Steel		
Category	Light Commercial Vehicle		
Oil level	OK		

Options

Radio CD	Central consol F
Windows electric F	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	225/70/15/110 C Steel			
Summer tyres:	Fr.L.	Pirelli: 1,5 mm	Fr.R.	Pirelli: 1,5 mm
	Re.L.	Pirelli: 2 mm	Re.R.	Pirelli: 2 mm

Assistance equipment

Spare wheel	Yes
-------------	------------

Total cost ex VAT	761,82
Sill outer L, Bump(s) and scratch(es), LI - Repair and paint (complete)	280,88



Wheel arch cover F R, Missing, E - Replace	69,00
--	-------



Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	------

No pictures to display	
Front bumper, Scratch(es), Acceptable	0,00

No pictures to display	
Aerial Damaged, E - Replace	11,25

Aerial, Damaged, L - Replace		11,25
		
Door R R, Bad repair, Paint		0,00
		
Door F L, Bump(s), Acceptable		0,00
No pictures to display		
Rearview mirror housing R, Scratch(es), Acceptable		0,00
No pictures to display		
Rear panel, Bump(s) and scratch(es), It - Spot repair		187,56
		
Interior, Damaged, Acceptable		0,00
		
Wing R L, Scratch(es), Acceptable		0,00
No pictures to display		
Bumper R, Scratch(es), Acceptable		0,00
No pictures to display		
Wing F L, Bump(s), LI - Repair and paint (complete)		213,13
		