



AUDI A3: 1HFX997			
Vinnnumber:	WAUZZZ8V7FA018285	Versionname:	A3 SB Attraction 105PK
First Registrationdate:	10/07/2014	Fiscalpower:	
Expertise Mileage:	100627	Power Kw:	77
Bodytype:	Hatchback	Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3116
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		


Options			
Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	NOT OK
Engine startingtime	OK	Lighting	NOT OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
Winter tyres:	205/55/16/91 H LightMetal			
	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			356,80
Wing R L, Scratch(es), Acceptable			0,00
No pictures to display			
Roof pillar R, Bad repair, Acceptable			0,00





Backrest cover F R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Wing F R, Bad repair, Acceptable	0,00
----------------------------------	------



Interior, Dirty, Cleaning	50,00
---------------------------	-------



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Rear spoiler, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Windscreen, Stone chip(s), Acceptable	0,00
---------------------------------------	------

No pictures to display

Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	------

No pictures to display

Roof, Scratch(es), Acceptable	0,00
-------------------------------	------

No pictures to display