



VOLVO XC60: 1FRI283			
Vinnnumber:	YV1DZ31A1E2537935	Versionname:	XC60 D3 Kinetic 136PK
First Registrationdate:	1/10/2013	Fiscalpower:	
Expertise Mileage:	100817	Power Kw:	100
Bodytype:	SUV	Body color	Silver
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2325
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
Winter tyres:	235/65/17/108 V LightMetal			
	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1046,00
Wing R R, Scratch(es), LI - Repair and paint (complete)			369,84



Front bumper, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Door panel R L, Damaged, E - Replace	132,00
--------------------------------------	--------



Alloy Rims (all), Rust, Acceptable	0,00
------------------------------------	------

No pictures to display

Rear window, Scratch(es), Acceptable	0,00
--------------------------------------	------

No pictures to display

Bumper R, Scratch(es), Le - Replace and paint	0,00
---	------



Rearlight L, Crack, E - Replace	132,00
---------------------------------	--------



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Roof, Scratch(es), LI - Repair and paint (complete)	0,00
---	------



Door F L, Bump(s), PDR - Knock out without painting	63,00
---	-------

