



RENAULT Clio: 1GIC258			
Vinnnumber:	VF15RJLOH50186498	Versionname:	CLIO IV BER e-Expression St&St 90PK
First Registrationdate:	13/02/2014	Fiscalpower:	
Expertise Mileage:	81981	Power Kw:	66
Bodytype:	Hatchback	Body color	Silver
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3528
Number of doors	5		
Number of seats	5		
Number head rests	4		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options	
GPS storage	HD Luggage cover
GPS storage	
Windows electric F	
Cruise Control	
Steering wheel multifunction	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
Winter tyres:	185/65/15/88 T Steel			
	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment	
Repair kit	Yes
Compressor	Yes
Total cost ex VAT	190,19
Bonnet, Scratch(es), Acceptable	0,00
No pictures to display	
Wing F L, Scratch(es), Acceptable	0,00
No pictures to display	
Door R R, Scratch(es), Acceptable	0,00
No pictures to display	
Wing R R, Scratch(es), Acceptable	0,00
No pictures to display	
Wheel cover F R, Scratch(es), E - Replace	24,00





Wheel cover F L, Scratch(es), E - Replace	24,00
---	-------



Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Rear window, Scratch(es), Acceptable	0,00
--------------------------------------	------

No pictures to display


Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rearview mirror housing L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door F L, Bump(s), PDR - Knock out without painting	63,00
---	-------



Wheel cover R L, Scratch(es), E - Replace	24,00
---	-------



Headlight R, Scratch(es), 67 - Polish	55,19
---------------------------------------	-------

