



PEUGEOT 5008: 1EIL105			
Vinnnumber:	VF30A9HD8CS267531	Versionname:	5008 e-HDi Active FAP
First Registrationdate:	13/12/2012	Fiscalpower:	BMP 115PK Aut.
Expertise Mileage:	176477	Power Kw:	84
Bodytype:	MPV	Body color	Grey
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2309
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options			
Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear			
Winter tyres:	215/55/16/93 H LightMetal		
	Fr.L.	Continental: 4 mm	Fr.R.
			Continental: 4 mm
	Re.L.	Uniroyal: 5 mm	Re.R.
			Uniroyal: 5 mm

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			1488,38
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)			95,00



Windscreen, Scratch(es), Acceptable	0,00
No pictures to display	

Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
	
Wing F R, Scratch(es), Acceptable	0,00
No pictures to display	
Wing R L, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
	
Internal Boot Lining L, Scratch(es), Acceptable	0,00
No pictures to display	
Rocker panel inner F R, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
	
	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
	
Rear spoiler, Scratch(es), Acceptable	0,00
No pictures to display	
Front bumper, Scratch(es), Acceptable	0,00
No pictures to display	
Steering wheel, Worn, Acceptable	0,00
No pictures to display	
Rear window, Scratch(es), E - Replace	0,00
	
Interior, Stain, Cleaning	125,00
	
  	



Roof, Chemical polution, LI - Repair and paint (complete)	481,50
---	--------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

