



|                                   |                   |              |                    |
|-----------------------------------|-------------------|--------------|--------------------|
| SEAT LEON ST: 1KDS119             |                   |              |                    |
| Vinnumber:                        | VSSZZZ5FZFR089879 | Versionname: | 1.6 TDI 77KW STYLE |
| First Registrationdate:           | 9/04/2015         | Fiscalpower: |                    |
| Expertise Mileage:                | 211695            | Power Kw:    | 77                 |
| Bodytype:                         | Break             | Body color   | Black              |
| Gearbox:                          | MAN 5 VIT         | Paint type   | Metalic            |
| Transmission:                     | Front             | Rims summer  | Aluminium          |
| Fueltype:                         | Diesel            | Oil level    | OK                 |
| Battery functioning               | Yes               | Parking lot  | 3621               |
| Number of doors                   | 5                 |              |                    |
| Number of seats                   | 5                 |              |                    |
| Number head rests                 | 5                 |              |                    |
| Rims summer                       | Aluminium         |              |                    |
| Category                          | Passenger Car     |              |                    |
| Oil level                         | OK                |              |                    |
| Registration Certificate Car (BE) | Yes               |              |                    |

|                                |                       |
|--------------------------------|-----------------------|
| Options                        |                       |
| Radio CD                       | Central consol F      |
| Windows electric F             | Luggage cover         |
| Windows electric R             | Front parking sensors |
| Cruise Control                 | Rear parking sensors  |
| Steering wheel multifunctional |                       |
| Radio multimedia               |                       |
| Type of headlighting           | Headlighting LED      |
| Type of GPS                    | GPS big screen color  |
| Type of Lining                 | Lining fabrics        |
| Type of climate control        | Autom climate control |


|                              |     |                     |     |
|------------------------------|-----|---------------------|-----|
| Limited Technical Inspection |     |                     |     |
| Power steering               | Yes | Battery functioning | Yes |
| Airco functioning            | OK  | Sound engine        | OK  |
| Tires wear profile           | OK  | Clutch test         | OK  |
| Idle position                | OK  | Wiper fluid level   | OK  |
| Engine startingtime          | OK  | Lighting            | OK  |
| Exhaust gass                 | OK  | Wiperblades         | OK  |
| Transmission                 | OK  |                     |     |
| Handbrake                    | OK  |                     |     |

|                |                           |                 |       |
|----------------|---------------------------|-----------------|-------|
| Degree of wear |                           |                 |       |
| Winter tyres:  | 205/55/16/91 H LightMetal |                 |       |
|                | Fr.L.                     | Firestone: 7 mm | Fr.R. |
|                |                           | Firestone: 7 mm |       |
|                | Re.L.                     | Firestone: 7 mm | Re.R. |
|                |                           | Firestone: 7 mm |       |

|                             |     |      |        |
|-----------------------------|-----|------|--------|
| Assistance equipment        |     |      |        |
| Emergency spare wheel       | Yes | Jack | Yes    |
| Total cost ex VAT           |     |      | 521,20 |
| Door R R, Bad repair, Paint |     |      | 0,00   |



|                                                   |       |
|---------------------------------------------------|-------|
| Bonnet, Bump(s), PDR - Knock out without painting | 63,00 |
|---------------------------------------------------|-------|



|  |        |
|--|--------|
|  | 122,00 |
|--|--------|

|                                                     |        |
|-----------------------------------------------------|--------|
| Ignition key, Missing, E - Replace                  | 150,00 |
| No pictures to display                              |        |
| Door R L, Scratch(es), Acceptable                   | 0,00   |
| No pictures to display                              |        |
| Bonnet, Scratch(es), Acceptable                     | 0,00   |
| No pictures to display                              |        |
| Wing R R, Bump(s), LI - Repair and paint (complete) | 308,20 |

