


**CITROEN C4 Picasso: 1FSK291**

|                                   |                          |              |                             |
|-----------------------------------|--------------------------|--------------|-----------------------------|
| Vinnnumber:                       | <b>VF7UA9HR8DJ711234</b> | Versionname: | <b>GR.C4 PICASSO</b>        |
| First Registrationdate:           | <b>10/10/2013</b>        | Fiscalpower: | <b>7pl.Seduct.FAP 112PK</b> |
| Expertise Mileage:                | <b>94743</b>             | Power Kw:    | <b>82</b>                   |
| Bodytype:                         |                          | Body color   | <b>Brown</b>                |
| Gearbox:                          | <b>MAN 6 VIT</b>         | Paint type   | <b>Metalic</b>              |
| Transmission:                     | <b>Front</b>             | Rims summer  | <b>Aluminium</b>            |
| Fueltype:                         | <b>Diesel</b>            | Oil level    | <b>OK</b>                   |
| Maintenance                       | <b>5100 KM</b>           | Parking lot  | <b>2730</b>                 |
| Maintenance                       | <b>OK</b>                |              |                             |
| Battery functioning               | <b>Yes</b>               |              |                             |
| Number of doors                   | <b>5</b>                 |              |                             |
| Number of seats                   | <b>7</b>                 |              |                             |
| Number head rests                 | <b>7</b>                 |              |                             |
| Rims summer                       | <b>Aluminium</b>         |              |                             |
| Category                          | <b>Passenger Car</b>     |              |                             |
| Oil level                         | <b>OK</b>                |              |                             |
| Registration Certificate Car (BE) | <b>Yes</b>               |              |                             |

**Options**

|                                |                              |                      |                          |
|--------------------------------|------------------------------|----------------------|--------------------------|
| Radio CD                       |                              | Central consol F     |                          |
| GPS storage                    | <b>HD</b>                    | Luggage cover        |                          |
| GPS storage                    |                              | Rear parking sensors |                          |
| Windows electric F             |                              | Type of Tow bar      | <b>Tow bar removable</b> |
| Windows electric R             |                              |                      |                          |
| Cruise Control                 |                              |                      |                          |
| Steering wheel multifunctional |                              |                      |                          |
| Radio multimedia               |                              |                      |                          |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                      |                          |
| Type of GPS                    | <b>GPS big screen color</b>  |                      |                          |
| Type of Lining                 | <b>Lining fabrics</b>        |                      |                          |
| Type of climate control        | <b>Autom climate control</b> |                      |                          |

**Limited Technical Inspection**

|                     |            |                     |            |
|---------------------|------------|---------------------|------------|
| Power steering      | <b>Yes</b> | Battery functioning | <b>Yes</b> |
| Airco functioning   | <b>OK</b>  | Sound engine        | <b>OK</b>  |
| Tires wear profile  | <b>OK</b>  | Clutch test         | <b>OK</b>  |
| Idle position       | <b>OK</b>  | Wiper fluid level   | <b>OK</b>  |
| Engine startingtime | <b>OK</b>  | Lighting            | <b>OK</b>  |
| Exhaust gass        | <b>OK</b>  | Wiperblades         | <b>OK</b>  |
| Transmission        | <b>OK</b>  |                     |            |
| Handbrake           | <b>OK</b>  |                     |            |

**Degree of wear**

|               |                                  |                     |       |                     |
|---------------|----------------------------------|---------------------|-------|---------------------|
|               | <b>215/55/16/93 H LightMetal</b> |                     |       |                     |
| Winter tyres: | Fr.L.                            | <b>Kleber: 5 mm</b> | Fr.R. | <b>Kleber: 5 mm</b> |
|               | Re.L.                            | <b>Kleber: 5 mm</b> | Re.R. | <b>Kleber: 5 mm</b> |

**Assistance equipment**

|                                                              |            |            |              |
|--------------------------------------------------------------|------------|------------|--------------|
| Repair kit                                                   | <b>Yes</b> | Compressor | <b>Yes</b>   |
| Total cost ex VAT                                            |            |            | <b>95,00</b> |
| Wing R R, Bump(s), Acceptable                                |            |            | <b>0,00</b>  |
| <i>No pictures to display</i>                                |            |            |              |
| Door R R, Bump(s), Acceptable                                |            |            | <b>0,00</b>  |
| <i>No pictures to display</i>                                |            |            |              |
| Bumper R, Scratch(es), Acceptable                            |            |            | <b>0,00</b>  |
| <i>No pictures to display</i>                                |            |            |              |
| Bonnet, Stone chip(s), Acceptable                            |            |            | <b>0,00</b>  |
| <i>No pictures to display</i>                                |            |            |              |
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) |            |            | <b>95,00</b> |



|                                   |      |
|-----------------------------------|------|
| Door F R, Scratch(es), Acceptable | 0,00 |
| No pictures to display            |      |
| Door R L, Scratch(es), Acceptable | 0,00 |
| No pictures to display            |      |