



AUDI A6: 1EPX190				
Vinnnumber:	WAUZZZ4G9DN104338	Versionname:	A6 AVANT 136PK	
First Registrationdate:	19/02/2013	Fiscalpower:		
Expertise Mileage:	177682	Power Kw:	100	
Bodytype:	Break	Body color	Dark Grey	
Gearbox:	MAN 6 VIT	Paint type	Metalic	
Transmission:	Front	Rims summer	Aluminium	
Fueltype:	Diesel	Oil level	OK	
Battery functioning	Yes	Parking lot	3507	
Number of doors	5			
Number of seats	5			
Number head rests	5			
Rims summer	Aluminium			
Category	Passenger Car			
Oil level	OK			
Options				
Radio CD		Central consol F		
Windows electric F		Luggage cover		
Windows electric R		Front parking sensors		
Cruise Control		Rear parking sensors		
Steering wheel multifunctional		Type of Tow bar	Tow bar fixed	
Seats F heated				
Radio multimedia				
Type of headlighting	Headlighting Halogen			
Type of GPS	GPS big screen color			
Type of Lining	Lining leather			
Type of climate control	Autom climate control			
Limited Technical Inspection				
Power steering	Yes	Battery functioning	Yes	
Airco functioning	OK	Sound engine	OK	
Tires wear profile	OK	Clutch test	OK	
Idle position	OK	Wiper fluid level	OK	
Engine startingtime	OK	Lighting	OK	
Exhaust gass	OK	Wiperblades	OK	
Transmission	OK			
Handbrake	OK			
Degree of wear				
	215/60/16/99 H LightMetal			
Winter tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm
Assistance equipment				
Repair kit	Yes	Compressor	Yes	
Total cost ex VAT			985,34	
Door F R, Scratch(es), LI - Repair and paint (complete)			382,02	
Wing R R, Scratch(es), Acceptable			0,00	
No pictures to display				
Front bumper, Scratch(es), LI - Repair and paint (complete)			254,16	



Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display