



BMW 5: 1FNT696

Vinnumber:	WBA5J11020D335631	Versionname:	5 TOURING 518d 136PK
First Registrationdate:	2/09/2013	Fiscalpower:	
Expertise Mileage:	139270	Power Kw:	100
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	5000 KM 6:2018	Parking lot	2302
Maintenance	OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Seats electric F L
GPS storage	HD	Seats electric F R
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	
Adaptive cruise control		

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	
Transmission	OK		
Handbrake	OK		

Degree of wear

225/55/17/97 H LightMetal				
Winter tyres:	Fr.L.	Continental: 6 mm	Fr.R.	
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1079,80
--------------------------	----------------

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
---	--------------



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20
--	---------------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Front bumper, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R R, Bump(s), PDR - Knock out without painting

63,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80

