


MERCEDES A: 1HKS119

Vinnnumber:	WDD1760121V027632	Versionname:	A 180CDI BE Edition 109PK
First Registrationdate:	12/08/2014	Fiscalpower:	
Expertise Mileage:	143637	Power Kw:	80
Bodytype:	Hatchback	Body color	Dark Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1410
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Manual climate control

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear


	205/55/16/91 T LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Uniroyal: 7 mm	Re.R.	Uniroyal: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1372,98
Wing F R, Scratch(es), Acceptable			0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------




Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------




Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Wing R R, Bad repair, Paint	0,00
-----------------------------	------



Roof, Bump(s) and scratch(es), LI - Repair and paint (complete)	481,50
---	--------



Roof pillar L, Bump(s), PDR - Knock out without painting	82,80
--	-------



Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete)	290,08
---	--------

