



VOLVO S60: 1GMZ862				
Vinnumber:	YV1FS8481E2311335	Versionname:	S60 BER D2 Kinetic 115PK	
First Registrationdate:	14/03/2014	Fiscalpower:		
Expertise Mileage:	110577	Power Kw:	84	
Bodytype:	Berline	Body color	Silver	
Gearbox:	MAN 6 VIT	Paint type	Metalic	
Transmission:	Front	Rims summer	Aluminium	
Fueltype:	Diesel	Oil level	OK	
Battery functioning	Yes	Parking lot	4426	
Number of doors	4			
Number of seats	5			
Number head rests	5			
Rims summer	Aluminium			
Category	Passenger Car			
Oil level	OK			
Registration Certificate Car (BE)	Yes			
Options				
Radio CD		Central consol F		
Windows electric F		Front parking sensors		
Windows electric R		Rear parking sensors		
Cruise Control				
Steering wheel multifunctional				
Radio multimedia				
Type of headlighting	Headlighting Halogen			
Type of GPS	GPS big screen color			
Type of Lining	Lining fabrics			
Type of climate control	Autom climate control			
Limited Technical Inspection				
Power steering	Yes	Battery functioning	Yes	
Airco functioning	OK	Sound engine	OK	
Tires wear profile	OK	Clutch test	OK	
Idle position	OK	Wiper fluid level	OK	
Engine startingtime	OK	Lighting	OK	
Exhaust gass	OK	Wiperblades	OK	
Transmission	OK			
Handbrake	OK			
Degree of wear				
Winter tyres:	215/50/17/95 V LightMetal			
	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Assistance equipment				
Repair kit	Yes	Compressor	Yes	
Total cost ex VAT			841,00	
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)			95,00	
				
Bodywork, Not original part, Acceptable			0,00	
No pictures to display				
Front bumper, Scratch(es), Acceptable			0,00	
No pictures to display				
Bumper R, Damaged, Le - Replace and paint			651,00	



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00

