


VOLKSWAGEN Passat: 1FAY530

Vinnnumber:	WVWZZZ3CZDE098946	Versionname:	PASSAT VAR Comfortline BMT 105PK
First Registrationdate:	13/05/2013	Fiscalpower:	
Expertise Mileage:	125022	Power Kw:	77
Bodytype:	Break	Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4601
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	215/55/16/93 H LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 7 mm	Fr.R.	Uniroyal: 7 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	2126,98
Door F R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Trunk lid covering R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Chemical polution, LI - Repair and paint (complete)	308,20




Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	--------



Roof, Chemical polution, LI - Repair and paint (complete)

481,50



Wing R L, Chemical polution, LI - Repair and paint (complete)

308,20




Bumper R, Damaged, Le - Replace and paint

651,00




Interior, Stain, Cleaning

25,00



Tailgate, Bump(s), PDR - Knock out without painting

63,00



Rearview mirror housing R, Scratch(es), Acceptable

0,00

No pictures to display