



VOLKSWAGEN Crafter 35 MWB hoog dak: 038APJ			
Vinnumber:	WV1ZZZ2EZ96034510	Versionname:	CRAFTER 35 B/F MWB HR 88pk
First Registrationdate:	20/05/2009	Fiscalpower:	
Expertise Mileage:	131295	Power Kw:	65
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	TRU12
Number of doors	5		
Number of seats	3		
Number head rests	3		
Rims summer	Steel		
Category	Light Commercial Vehicle		
Oil level	OK		

Options		
Radio CD	Type of Tow bar	Tow bar fixed
Windows electric F		
Cruise Control		
Type of headlighting	Headlighting Halogen	
Type of Lining	Lining artificial leather	
Type of climate control	Manual climate control	
Adaptive cruise control		

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear			
Winter tyres:	235/65/16/115 R Steel		
	Fr.L.	Goodyear: 4 mm	Fr.R. Goodyear: 4 mm
	Re.L.	Goodyear: 4 mm	Re.R. Goodyear: 4 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			1250,43
Tailgate, Rust, LI - Repair and paint (complete)			362,02



Seat cover F L, Damaged, Acceptable	0,00
-------------------------------------	------



Wing R L, Rust, LI - Repair and paint (complete)	231,15
--	--------



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	231,15
---	--------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Mirror side blinker L, Damaged, E - Replace	28,50
---	-------



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	238,76
---	--------



Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bonnet, Bump(s), Acceptable	0,00
-----------------------------	------

No pictures to display

Front bumper, Bump(s), LI - Repair and paint (complete)	158,85
---	--------

