



VOLKSWAGEN Passat: 1ERW856			
Vinnnumber:	WVWZZZ3CZDE097754	Versionname:	PASSAT VAR Comfortline BMT 105PK
First Registrationdate:	5/03/2013	Fiscalpower:	
Expertise Mileage:	79623	Power Kw:	77
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3329
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options			
GPS storage	HD	Sun Roof electric	
GPS storage		Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	Tow bar removable
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
Summer tyres:	215/55/16/91 V LightMetal			
	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm

Assistance equipment	
Spare wheel	Yes
Jack	Yes
Total cost ex VAT	844,35
Roof, Bump(s), Acceptable	0,00
No pictures to display	
Wing R L, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Bonnet, Bump(s), Acceptable	0,00
No pictures to display	

Trunk lid covering R, Scratch(es), Smart repair	110,64
	
Door F L, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper F R, Scratch(es), It - Spot repair	115,56
	
Door R R, Scratch(es), LI - Repair and paint (complete)	318,35
	
Boot carpet, Dirty, Cleaning	25,00
	
Door R L, Bump(s), Acceptable	0,00
No pictures to display	
Wing R R, Bump(s), Acceptable	0,00
No pictures to display	
Roof, Bump(s), PDR - Knock out without painting	63,00
	