


SKODA Octavia: 1HAB039

Vinnnumber:	TMBJG9NEXE0221752	Versionname:	OCTAVIA COMBI Elegance
First Registrationdate:	2/06/2014	Fiscalpower:	105PK
Expertise Mileage:	54317	Power Kw:	77
Bodytype:	Break	Body color	Grey
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	SERVICE IN 24400 KM	Parking lot	2119
Maintenance	OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage	HD	Seats electric F L
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	225/45/17/91 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	498,20
-------------------	--------

Outer door handle F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Headlight L, Not functioning (well), P - Check	0,00
--	------

No pictures to display

Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
	
Wing R L, Bump(s), Acceptable	0,00
No pictures to display	
Front bumper, Stone chip(s), Acceptable	0,00
No pictures to display	
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
	
Bonnet, Stone chip(s), Acceptable	0,00
No pictures to display	
Door R L, Bump(s), Acceptable	0,00
No pictures to display	
Bumper R, Repaired, P - Check	0,00
No pictures to display	
Alloy rim F R, Scratch(es), Acceptable	0,00
No pictures to display	