



VOLKSWAGEN Jetta: 1HAU122			
Vinnumber:	WVWZZZ16ZEM001527	Versionname:	JETTA BER 1.6CRTDi
First Registrationdate:	5/06/2014	Fiscalpower:	Comfort BMT 105PK
Expertise Mileage:	137953	Power Kw:	77
Bodytype:	Berline	Body color	Black
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2332
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		
Options			
Radio CD		Central consol F	
GPS storage	HD	Front parking sensors	
GPS storage		Rear parking sensors	
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		
Degree of wear			
Summer tyres:	205/55/16/91 H LightMetal		
	Fr.L.	Michelin: 4 mm	Fr.R.
	Re.L.	Michelin: 5 mm	Re.R.
		Michelin: 4 mm	Michelin: 5 mm
Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			2244,34
Seat cover F L, Stain, Cleaning			25,00
 			
Alloy rim F L, Damaged, E - Replace			235,20



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Roof pillar R, Chemical pollution, LI - Repair and paint (complete) 220,18



Wing R L, Bad repair, Acceptable 0,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Armrest R M, Deformed, Acceptable 0,00



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18






Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Damaged, E - Replace 235,20



		Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
		Wing R R, Bump(s), PDR - Knock out without painting	159,00
		Door F L, Scratch(es), Acceptable	0,00
No pictures to display			
		Roof, Chemical polution, LI - Repair and paint (complete)	481,50
		Rearview mirror L complete, Damaged, Le - Replace and paint	283,00
		Front bumper, Scratch(es), Acceptable	0,00
No pictures to display			