



OPEL Astra: 1EUJ468			
Vinnnumber:	WOLPE8EW8D8045415	Versionname:	ASTRA BRE ecoFLEX Cosmo St/St 110PK
First Registrationdate:	22/03/2013	Fiscalpower:	
Expertise Mileage:	129402	Power Kw:	81
Bodytype:		Body color	Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2111
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Winter tyres:	225/50/17/94 H LightMetal			
	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			64,32
Door F R, Bump(s), Acceptable			0,00
No pictures to display			
Bumper F L, Scratch(es), Acceptable			0,00
No pictures to display			
Rocker panel inner F L, Scratch(es), Acceptable			0,00
No pictures to display			
Windscreen, Stone chip(s), P - Check			0,00
No pictures to display			
Door F L, Bump(s), Acceptable			0,00
No pictures to display			
Wing R L, Scratch(es), Acceptable			0,00
No pictures to display			
Roof pillar R, Bump(s), Acceptable			0,00
No pictures to display			

Wing R R, Bump(s), Acceptable	0,00
No pictures to display	
Bumper R, Scratch(es), Acceptable	0,00
No pictures to display	
Tailgate, Bump(s), Acceptable	0,00
No pictures to display	
Seat cover F L, Scratch(es), Smart repair	64,32

