



OPEL Astra: 1FJG090			
Vinnnumber:	W0LPC6DA3D1126217	Versionname:	ASTRA BER ecoFLEX
First Registrationdate:	15/07/2013	Fiscalpower:	Essentia S&S 95PK
Expertise Mileage:	179524	Power Kw:	70
Bodytype:	Break	Body color	Brown
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3118
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	Luggage cover
Windows electric F	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Winter tyres:	215/60/16/99 H Steel			
	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			608,43
Wing R R, Scratch(es), Acceptable			0,00
No pictures to display			
Door F L, Scratch(es), LI - Repair and paint (complete)			318,35



Bumper R, Accident, Le - Replace and paint	0,00
--	------



Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	--------

