



MERCEDES A: 1GKF631			
Vinnnumber:	WDD1760121J250841	Versionname:	A 180 CDI BE 109PK
First Registrationdate:	3/03/2014	Fiscalpower:	
Expertise Mileage:	111204	Power Kw:	80
Bodytype:	Hatchback	Body color	Dark Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1313
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear			
Winter tyres:	195/65/15/91 T Steel		
	Fr.L.	Bridgestone: 3 mm	Fr.R. Bridgestone: 3 mm
	Re.L.	Bridgestone: 4 mm	Re.R. Bridgestone: 4 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			210,00
Wing R R, Bad repair, Paint			0,00



Bumper R, Bad repair, Paint	0,00
-----------------------------	------




Wheel cover F L, Scratch(es), E - Replace	30,00
---	-------



Wheel cover R R, Scratch(es), E - Replace	30,00
---	-------



Wing R L, Bad repair, Paint	0,00
-----------------------------	------



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display