



MERCEDES C220: 1GMC896			
Vinnumber:	WDD2040021A942587	Versionname:	DIESEL
First Registrationdate:	7/03/2014	Fiscalpower:	
Expertise Mileage:	82394	Power Kw:	120
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	1128
Maintenance	A DANS 22400KM		
Battery functioning	Yes		
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options	
Radio CD	Seats electric F L
GPS storage HD	Seats electric F R
GPS storage	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-artificial leather

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear			
Winter tyres:	205/55/16/91 H LightMetal		
	Fr.L.	Goodyear: 7 mm	Fr.R.
	Re.L.	Goodyear: 6 mm	Re.R.
		Goodyear: 7 mm	Goodyear: 5 mm

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			25,00
Bumper R, Scratch(es), Acceptable			0,00



Door R R, Bump(s), Acceptable	0,00
-------------------------------	------



Alloy rim R L, Scratch(es), Acceptable

0,00



Alloy rim F L, Scratch(es), I - Repair

0,00



Door F L, Scratch(es), Acceptable

0,00



Seat cover F L, Stain, Cleaning

25,00



Alloy rim F R, Scratch(es), Acceptable

0,00



Wing F L, Bump(s), Acceptable

0,00



Bonnet, Stone chip(s), Acceptable

0,00



Alloy rim R R, Scratch(es), Acceptable

0,00

