



OPEL Astra: 1EJR550			
Vinnnumber:	W0LPD8EA0D8019088	Versionname:	ASTRA BRE ecoFLEX Enjoy St/St 95PK
First Registrationdate:	1/01/2013	Fiscalpower:	
Expertise Mileage:	178160	Power Kw:	70
Bodytype:	Break	Body color	Blue
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2502
Number of doors	5		
Number of seats	5		
Number head rests	4		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD Front parking sensors
Windows electric F	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear			
Winter tyres:	205/60/16/96 H Steel		
	Fr.L.	Fr.R.	Michelin: 6 mm
	Re.L.	Re.R.	Michelin: 4 mm

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			88,20
Floor covering F L, Hole, Acceptable			0,00




Door F L, Scratch(es), Acceptable	0,00
No pictures to display	
Front bumper, Chemical polution, Paint	0,00





Windscreen, Stone chip(s), Windscreen repair	88,20
--	-------



Wing R R, Bad repair, Paint	0,00
-----------------------------	------



Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bonnet, Chemical polution, Acceptable	0,00
---------------------------------------	------



Bumper R, Bad repair, Paint	0,00
-----------------------------	------

